


Status check

Press  for 1 second. The LED lights turn on



Power ON

Press  for 5 seconds until the **REC** light turns **GREEN**.

The REC light will show the status.

REC: LED light code



ON



OFF



Placement



Stick the envelope with the sensor on pallet 19 or 20, next to the identification labels.



Insert the sensor and the label into the envelope. Place the sensor with the front side facing outwards (logo visible).



Make holes in the envelope and attach the second label next to it.